

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-033 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 20, 2006

Debra Nelson, Administrator 1970 East 17th Street #103 Idaho Falls, ID 83404

License #: RC-692

Dear Ms. Nelson:

On September 21, 2006, a life safety code survey was conducted at Rosetta Assisted Living - Pendlebury. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire, Life Safety, and Construction Program

EM/slc

c:

Mark Grimes, Supervisor, Facility Fire, Life Safety, and Construction Program



JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6526 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 5, 2006

Debra Nelson, Administrator Rosetta Assisted Living - Pendlebury 1970 East 17th Street #103 Idaho Falls, ID 83404

FILE COPY

Dear Ms. Nelson:

On September 21, 2006, a life safety code survey was conducted at Rosetta Assisted Living - Pendlebury. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by October 21, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely.

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED **IDENTIFICATION NUMBER:** A. BUILDING 01 - ENTIRE BUILDING B. WING 13R692 09/21/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 875 S PENDLEBURY **ROSETTA ASSISTED LIVING - PENDLEBURY** BLACKFOOT, ID 83221 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE DATE (X4) ID (EACH DEFICIENCY MUST BE PRECEEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PRÉFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on September 21, 2006. The surveyor conducting the survey was: Eric Mundell REHS Health Facility Surveyor Facility Fire Safety & Construction

Bureau of Facility Standards

TITLE

(X6) DATE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888 ASSISTED LIVING Non-Core Issues Punch List

Facility Name Rosetta - Pendlebung	Physical Address 875 S Pendleburg	Phone Number 785 3627
Administrator D Nelson	Blackbout	ZIP Code 8322/
Survey Team Leader En I Mun It!	Survey Type Fire / Life Sofety	Survey Date 9 /21/06
NON-CORE ISSUES	DESCRIPTION	, DATE

NON-CORE ISSUES				
ITEM	RULE#	DESCRIPTION	DATE RESOLVED	
#	是是对性的特殊的现在分词。		///	
<i>f</i>	10.03.22.415.01	Main Frince Sufely: Water was leaking from an un-	60/17/06	
		Known Source in the eyesponent/firence own.	Gan	
		There was standing natur on the flow and the		
		Tinoleum was peeling from the Subfleer Surpace.	<u> </u>	
2_	16.03. 22.750.01		10/17/06	
		review to show fire drills had been conducted in	An	
		2006.	1000	
*3	16.03.72,750.05	6. Fire alarm testing: There was no decrementation	10/17/06	
		to snow that the fine alarm had been tested	Em	
£		monthly since November 2005.		
U	16.03.22.750.00	Sprinkler System Service / testing ! There was no	10/17/06	
		report maintained on like to show results of the	gim	
		automatic fin sprinkler testing (Service done in		
	,	2006. RECEIVE	***	
		OCT 10 2006		
	he Required Date	Signature of Facility Representative FACILITY STANDAR	DS	